



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

MARY ANN WRIGHT
Acting Division Director

Supervisor ADP

Inspection Report
Minerals Regulatory Program
Report Date: February 25, 2005

Mine Name: Witt Excavating Sandstone Quarry
Operator or Permittee Name:
Witt Excavating
Permittee Mailing Address:
1245 South 1200 West, Heber City, Utah 84032

Permit number: M/051/006
Inspection Date: February 2, 2005

Inspector(s): Lynn Kunzler, Daron Haddock,
Beth Erickson
Other Participants: None

Weather: Clear
Inspection Start Time: 9:30 a.m.
Inspection End Time: 10:30 a.m.
Site location/Area Inspected (i.e. Pit #):
All
Surface Ownership: Fee
Mineral Ownership: Fee
Mineral Mined: Rock
Type of Mine: Surface quarry

Permit Status: Reclaimed
Current Acreages: 1
Total Permitted (Bonded): 0
Total Disturbed: 1

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:


To follow up on citizen complaint about potential mining in the area - DOGM had no active permit for area in question.

Inspection Summary:

1. Permits: No equipment was on site, however, it was evident that mining related activities have been conducted on site within the last week or two. This site has not been permitted with the Division.
6. Roads: The access road to the site showed evidence of recent use, as well as maintenance activities. This road was moderately rutted from heavy traffic during wet periods.
12. Soils: This is an old quarry area. No soil materials have been salvaged. The quarry has historically disturbed an estimated 1-1.5 acres. There has not been a lot of material removed over the years.

As a result of this inspection, it was determined that recent mining activities have been conducted at this site. Since this site was not permitted, a cessation order was issued and left at the residence of the land owner (about 4 blocks west of the access road to the quarry).

Inspector's Signature



Date: February 25, 2005

LK:jb

cc: Russell Witt, Witt Excavating

O:\M051-Wasatch\S0510006-witt\inspections\insp-02022005.doc